

F13

OFFICE OF THE ASSISTANT ENGINEER (C) CPWD JAISALMER

F- KVBSF/AE/JM/23(104) / Camp.

Date: 29.08.2020

STUCTURAL SAFETY CERTIFICATE

Name of Building : KENDRIYA VIDYALAYA BSF DABLA, JAISALMER

Year of Construction: 2006-07

Certified that the above said school building is inspected on 29.08.2020 by me, during inspection the building is found structurally safe & sound as per visual appearance , for users with reference to Principal KV BSF Dabla letter No F-13/KVD/2019-20/86 dated 21.07.2020

This certificate is being issued for one year.


Assistant Engineer-II

Jaisalmer Central Sub- Division
CPWD- Jaisalmer